



Date of Issue: 4/30/2024 Report Number: 24-000941

Revision Number:1

Date Order Received: 04/16/2024

For the Account of: Gabriel A/S

Hjulmagervej 55

9000 Aalborg Denmark

Client's Identification: TwillWool col.2001

CERTIFICATE OF TESTING

TEST PERFORMED: Resistance to Slippage of Yarns in Woven Fabrics Using a Standard Seam ASTM D4034-92

TEST RESULTS

Specimen	Warp Yarn Slippage (lbf)	Type of Failure	Specimen	Fill Yarn Slippage (lbf)	Type of Failure
1	49.2	SS	1	117.0	SB
2	46.6	SS	2	118.0	SB
3	37.3	SS	3	109.0	SB
4	35.4	SS	4	102.0	SB
5	48.9	SS	5	110.0	SB
Avg. Warp	43.5		Avg. Fill	111.0	

ABBREVIATIONS USED

SB Seam broke before 1/4" slippage - Results should reflect this

SS 1/4" slippage occurred - Note: Actual slippage of yarns is visible

FB Fabric broke before 1/4" slippage - Note: Actual breakage is visible

NOTES

Equipment Used: Tinius Olson H5KT Universal Testing Machine

Seam Description:

Seam TypeStandard LockstitchStitches per Inch 7 ± 0.5 stitches per inch

Needle Used Size 22 NM: 140, 135x17 ball point needle

Thread Nymo EX Bonded Nylon thread; 5x is used for the bobbin and 8x is used for the needle

ACCEPTANCE CRITERIA

A.C.T. Standard Acceptance Criteria
Upholstery 25 lbs. Minimum

CERTIFICATION I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Berta Stiver

Authorized Signature Date Order Completed: 04/25/2024