



Date of Issue: 3/20/2023 Report Number: 23-000835

Revision Number:1

Date Order Received: 03/14/2023

For the Account of: Gabriel A/S

Hjulmagervej 55 9000 Aalborg Denmark

Client's Identification: Beyond Loop 66086

## **CERTIFICATE OF TESTING**

**TEST PERFORMED:** Pilling Resistance and Other Related Surface Changes of Textile Fabrics: Brush Pilling Tester ASTM D3511/D3511M-16

## **TEST RESULTS**

	Rating
Left	5.0
Center	5.0
Right	5.0
Average Rating	5.0

## **RATING SYSTEM**

Class 5.0 No Pilling
Class 4.0 Slight Pilling
Class 3.0 Moderate Pilling
Class 2.0 Severe Pilling
Class 1.0 Very Severe Pilling

**NOTES** 

**Test Conditions:** 70 ±4°F, 65 ±5% Relative Humidity

Sampling Method: As Received
Viewing Apparatus: Macbeth Lightbooth

Viewing Option: 45 degree

Rating Standard: ADJD3512 Photographic Standards
Running Times: 4 minutes brushing / 2 minutes pilling

## **ACCEPTANCE CRITERIA**

A.C.T. Standard: Acceptance Criteria
Upholstery Class 3 minimum

**CERTIFICATION** I certify that the above results were obtained after testing specimen in accordance with the procedures and equipment specified by the standard stated above.

Authorized Signature

Date Order Completed: 03/17/2023

553 76th Street, Byron Center, MI 49315

P: 616-559-6123 E: testlab@applied-lab.com

Page 1 of 1

This laboratory test is not intended to reflect fabric performance under actual conditions. The certification procedure merely measures the performance of samples as received under the predetermined and specific test conditions prescribed by the standard specified. This certificate applies only to the standards or processing identified and to the random sample(s) tested. The test results are representative of the qualities of the piece or lot only to the extent the sample tested is representative of the piece or lot.